

January 2nd, 2007

Technical Service Bulletin

Products Affected: Marti PNP 1000 FM Transmitter
Description: First Up Converter (p/n 919-0483)

Dear Marti Customer:

This bulletin is to inform our users of a design improvement to the first up converter sub assembly in the PNP 1000 FM Transmitter.

Tests results have shown that Q3 may over dissipate, which will cause the transistor to fail and prevent the 73MHz (Y1) crystal on the 1st up converter from starting up properly.

All units shipped from Marti Electronics after November 29th, 2006, will have the enhanced circuitry to prevent a Q3 failure of this nature. Failures associated to Q3 on the first up converter sub assembly in the PNP 1000 FM Transmitter will be covered by Marti Electronics at no charge, excluding applicable shipping/handling fees. Contact the customer service department at service@martielectronics.com or 217-224-9617 for further information.

If you would like to be immediately notified by email when technical service bulletins are released, please register online using the following link. When completing the form, be sure to check the box next to BE Technical Updates.

<http://www.bdcast.com/bulletins/maillinglists/index.php>